

The following Notice to Mariners is published for general information

**Australia – Victoria****No. 219 (T) - 2026****PORT OF MELBOURNE  
ROCKY POINT  
DIRECTIONAL LIGHT UNRELIABLE****Date:** 5 April 2026**Refers:** N/A**Details:** Mariners are advised that the following aid to navigation light has been reported overly bright and flickering:


Beacon	ADLL Number	Position	Characteristic
Rocky Point directional light	K 2196	38° 16.62' S 144° 37.10' E	Dir F.AI.WR.3s 12m 6/4M

**Mariners are advised to navigate with additional caution.**

For further information, please email the Navigation Services department at [NavigationServices@ports.vic.gov.au](mailto:NavigationServices@ports.vic.gov.au) or contact Melbourne VTS on 9644 9700 / VHF Channel 12.

**Charts & Publications affected:** Aus 143, Aus 144  
ENC AU5RIP01  
Admiralty Digital List of Lights, Area 7, Volume K**Further notice:** Further notice will be issued

**David Tilsley  
Deputy Harbour Master  
Melbourne**



NOT FOR NAVIGATIONAL USE