

VICTORIAN NOTICE TO MARINERS

Port of Hastings

No. 199(T) - 2026

Port of Hastings – Sandy Point Buoy Day Shape Missing

Date: 26 March 2026

Refers: N/A

Details: Mariners are advised that the Sandy Point Buoy in position 38°24.5124'S 145°14.4880'E is currently missing the day shape.

The day shape will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the buoy.


Further information, please contact Hastings Marine Control VHF Channel 14 or 52253565.

Charts & Publications affected AUS 151 & 152
ENC AU5HIN01


Further notice: Further notice will be issued.



Paul Rasmussen
Deputy Harbour Master
Port of Geelong & Regional



NOT FOR NAVIGATIONAL USE



Victorian Notices to Mariners can be downloaded from the
Ports Victoria website www.ports.vic.gov.au