

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information

Australia – Victoria

No. 470 (T) - 2025

PORT OF MELBOURNE

YARRAVILLE 6

BERTH REMEDIATION WORKS

Date: 18 September 2025

Refers: N/A

**Details:** Mariners are advised that berth remediation works, involving under wharf works

and diving operations, will be undertaken at Yarraville 6 berth from 22

September 2025 until further notice.

Works will be conducted from 0700 hrs to 1700 hrs around shipping.

The following conditions will apply for diving operations and works:

- When diving operations and / or under wharf works are within 50m of a berthed commercial vessel (SOLAS), the vessel is to be notified by the works contractor.
- 30 minutes prior to a commercial vessel (SOLAS), including the bunker vessel, arriving or departing at Maribyrnong No. 1 berth, Yarraville 5 or 6 berth, under wharf works and diving operations to cease.
- 3. **30 minutes** prior to a **commercial vessel (SOLAS)**, including the bunker vessel **passing within 50m** of the works area, **under wharf works and diving operations to cease.**
- 4. **No diving operations** will take place when **bunkering** is being conducted at **Yarraville 5 or 6 berth.**
- 5. International Code flag Alpha displayed during diving operations.

Restrictions for passing **domestic commercial vessels** and **recreational vessels** during **works**:

- Minimum wake and wash
- Minimum passing distance of 50m

Vessels supporting works can be contacted on VHF Channel 12.

Mariners are advised to navigate with additional caution in the vicinity of Yarraville 6 berth during works.

For further information, please email the Navigation Services department at <a href="mailto:NavigationServices@ports.vic.gov.au">NavigationServices@ports.vic.gov.au</a> or contact Melbourne VTS on 9644 9700 / VHF Channel 12.

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)


The requirements of section 232(2) have been taken into account.

Charts & Publications affected:

**ENC AU5MEL01** 

Further notice: Further notice will be issued

David Tilsley Deputy Harbour Master Port of Melbourne



**NOT FOR NAVIGATIONAL USE** 

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)

The requirements of section 232(2) have been taken into account.