

The following Notice to Mariners is published for general information

Australia – Victoria**No. 231 - 2026****PORT OF MELBOURNE
PORT PHILLIP
SPECIAL MARK BUOY V2****Date:** 15 April 2026**Refers:** N/A**Details:** Mariners are advised that **special mark buoy V2** in the following position, has been removed and is **permanently withdrawn**:


Identification marking	Latitude	Longitude	Light characteristic
V2	38° 2.370' S	144° 47.470' E	Fl Y 4s

The **special mark buoys V3** (38° 3.377' S, 144° 47.700' E) and **V4** (38° 2.631' S, 144° 49.553' E) remain on station and will be removed at a later date.

For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au.

Charts & Publications affected: AUS 143, AUS 157
ENC AU5MEL01**Further notice:** No further notice will be issued

David Tilsley
Deputy Harbour Master
Melbourne



NOT FOR NAVIGATIONAL USE