

The following Notice to Mariners is published for general information


Australia – Victoria**No. 240 - 2026****PORT OF MELBOURNE****PORT PHILLIP****SPECIAL MARK BUOYS V3 & V4****Date:** 20 April 2026**Refers:** N/A**Details:** Mariners are advised that **special mark buoys V3 and V4** in the following positions, have been removed and are **permanently withdrawn**:

Identification marking	Latitude	Longitude	Light characteristic
V3	38° 3.367' S	144° 47.700' E	Fl Y 4s
V4	38° 2.617' S	144° 49.550' E	Fl Y 4s

For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au.

Charts & Publications affected: AUS 143, AUS 157
ENC AU5MEL01**Further notice:** No further notice will be issued

David Tilsley
Deputy Harbour Master
Melbourne



NOT FOR NAVIGATIONAL USE